roadside pylon sign drawing

Job summary: - One building sign.
- Supply and install new faces in existing pylon.

Revision 3 12/8/10

CITI TRENDS

Supply and install new sign faces in existing pylon:
(divider bars will need to be removed for new larger faces)
- 9 year translucent vinyl graphics.
- (2) faces, one for each side of pylon.
- 3/16" acrylic.

Citi Trends Store
Springdale Plaza S/C
455 East Kemper Rd.
Cincinnati, OH 45246

brandrite™ SIGN COMPANY INC.
803-533-7446
313 John C Calhoun Drive
Orangeburg SC 29115
Linford Oberholtzer
lin@brandritesign.com
Mobile 803-707-4512